## - Site Service Report -

IRD SO.: 11167 IRD Contract No.:

From: Jeff Wourms To: ESS

State: Indiana

Project Name/Location: Plymouth US31 NB MM 217.0

Service Date(s): Wednesday December 2, 2009

Job Description: Check modem and perform annual site inspection.

Work Completed: Drive to site.

Check phoneline in cabinet and on pole, working and good clean signal. Modem lights were all stuck on, cycled power & had IRD Saskatoon dial in. Modem appears to be slowing down & dropping the call, modem should be replaced in future.

Test all loops and Kistlers.

Loops 1-4 could be respliced, and Kistler #11+12 (NB left lane, trailing ½ strip) have weak readings and should be replaced.

Drive home.

Work Remaining: Replace modem. Replace Kistler #11 + 12.

## Parts Used:

Part Name	Part Number	Quantity Used

Mileage: 185 miles Hours Worked: 5 hours

Notes: Pictures below

## **Action Items:**


Item	Action Required	Ownership
1.		
2.		
3.		
4.		

6/19/96 IRD FORM No.: 1304A

Lane1 upstream:



Lane 1 downstream:




Lane 2 Upstream:



Lane 2 Downstream:



Lane 3 upstream:



Lane 3 downstream:



Lane 4 upstream:



